



| ISO | Descrizione                  | MORSE | D  | L   |
|-----|------------------------------|-------|----|-----|
| 50  | ISO50 DIN2080 H45 CM1 FRESE  | 1     | 25 | 45  |
| 50  | ISO50 DIN2080 H60 CM2 FRESE  | 2     | 32 | 60  |
| 50  | ISO50 DIN2080 H65 CM3 FRESE  | 3     | 40 | 65  |
| 50  | ISO50 DIN2080 H65 CM4 FRESE  | 4     | 48 | 65  |
| 50  | ISO50 DIN2080 H120 CM5 FRESE | 5     | 63 | 120 |

| ISO | Descrizione                  | MORSE | L   | D  | D2 |
|-----|------------------------------|-------|-----|----|----|
| 50  | ISO50 DIN2080 H115 CM1 FRESE | 1     | 115 | 18 | 25 |
| 50  | ISO50 DIN2080 H115 CM2 FRESE | 2     | 115 | 25 | 32 |
| 50  | ISO50 DIN2080 H115 CM3 FRESE | 3     | 115 | 33 | 40 |
| 50  | ISO50 DIN2080 H165 CM4 FRESE | 4     | 165 | 40 | 48 |
| 50  | ISO50 DIN2080 H200 CM5 FRESE | 5     | 200 | 55 | 63 |